

SHIMANO


SHIMANO (EUROPA) GmbH.
Kleinhülsen 1-3 40724 Hilden, Germany
Tel. 02103-5005-0

SHIMANO AMERICAN CORPORATION
One Shimano Drive, P.O. Box 19615, Irvine,
California U.S.A. 92713-9615 Tel. (714) 951-5003

Small parts list for after market.

- You may photocopy this sheet and use it as an order form.
- Sie können dieses Blatt kopieren und als Bestellformular verwenden.
- Vous pouvez photocopier cette feuille et l'utiliser comme bon de commande.
- Dit blad kan gecopieerd en als bestelformulier gebruikt worden.
- Potete fotocopiare questo foglio e usarlo come modulo di commissione.

SHIMANO RSX Freehub FH-A410 7-Speed



• Use with CS-HG50-C7.

	Q'TY	ITEM NO.	PART NO.	DESCRIPTION	WEIGHT / PACK (g)	Q'TY / PACK
		1	3AV 9012	Complete Quick Release 159 mm (6-1/4") for O.L. 126 mm (4-31/32")	86	1
			3AV 9013	Complete Quick Release 163 mm (6-13/32") for O.L. 130 mm (5-1/8")	88	1
		2	3AV 9801	Complete Hub Axle 137 mm (5-13/32") for O.L. 126 mm (4-31/32")	460	5
			3AV 9802	Complete Hub Axle 141 mm (5-9/16") for O.L. 130 mm (5-1/8")	476	5
		3	220 0501-1	Serrated Lock Nut 4.5 mm	56	10
		4	301 0710	Right Hand Washer 1.5 mm	18	10
		5	3AP 9803	Right Hand Axle Spacer Unit	72	10
		6	377 1000	Right Hand Seal Ring	6	10
		7	3AE 0300	Right Hand Cone M10 x 9 mm	66	10
		8	30K 0100	Hub Axle 137 mm (5-13/32") for O.L. 126 mm (4-31/32")	470	10
			30K 0110	Hub Axle 141 mm (5-9/16") for O.L. 130 mm (5-1/8")	486	10
		9	220 9808	Left Hand Cone (M10 x 15.1 mm) & Left Hand Seal Ring	138	10
		10	299 0500	Left Hand Seal Ring	8	10
		11	220 0460	Left Hand Axle Spacer 4 mm for O.L. 130 mm (5-1/8")	44	10
		12	301 0810	Left Hand Washer 1.2 mm	14	10
		13	359 0400	Body Fixing Bolt	138	10
		14	000 9131	Steel Ball (1/4") 18 pcs.	20	1
		15	3AP 9802	Complete Freewheel Body w/Right Hand Dust Cap	120	1
		16	375 0400	Freewheel Body Washer	22	10
		17	248 0500	Left Hand Dust Cap	38	10

O.L.: Over Lock Nut Dimension

02 Printed in Japan 9410-1508A