

SHIMANO

SHIMANO (EUROPA) GmbH.
Kleinhülsen 1-3 4010 Hilden, Germany
Tel. 02103-5005-0


SHIMANO AMERICAN CORPORATION
One Shimano Drive, P.O. Box 19615, Irvine,
California U.S.A. 92713-9615 Tel. (714) 951-5003

Small parts list for after market.

- You may photocopy this sheet and use it as an order form.
- Sie können dieses Blatt kopieren und als Bestellformular verwenden.
- Vous pouvez photocopier cette feuille et l'utiliser comme bon de commande.
- Dit blad kan gecopieerd en als bestelformulier gebruikt worden.
- Potete fotocopiare questo foglio e usarlo come modulo di commissione.

SHIMANO 400CX Freehub

FH-C040-7 For 7-Speed



• Use with CS-HG50-C7.

O.L.: Over Lock Nut Dimension

Q'TY	ITEM NO.	PART NO.	DESCRIPTION
	* 1	30M 9803	Complete Quick Release 161mm(6-11/32") for O.L. 130mm(5-1/8")
		30M 9804	Complete Quick Release 166mm(6-17/32") for O.L. 135mm(5-5/16")
	* 2	30M 9802	Complete Hub Axle 141mm(5-9/16") for O.L. 130mm(5-1/8")
		30M 9805	Complete Hub Axle 146mm(5-3/4") for O.L. 135mm(5-5/16")
	3	220 0502-1	Right Hand Lock Nut 3.5mm
	4	301 0710	Right Hand Washer 1.6mm
	5	30G 0300	Right Hand Cone M10 x 15mm
	* 6	30K 0110	Hub Axle 141mm(5-9/16") for O.L. 130mm(5-1/8")
		30K 0120	Hub Axle 146mm(5-3/4") for O.L. 135mm(5-5/16")
	7	220 0820-2	Left Hand Cone (M10 x 15mm)
	8	301 0810	Left Hand Washer 1.2mm
	9	220 0460	Left Hand Axle Spacer 4mm
	10	220 0501-1	Left Hand Lock Nut 4.5mm
	11	359 0400	Freewheel Body Fixing Bolt
	12	000 9131	Steel Ball (1/4") 18 pcs.
	13	30M 9801	Complete Freewheel Body w/Right Hand Dust Cap
	14	248 0500	Left Hand Dust Cap